



# CHECKMATE WHEEL NUT INDICATORS

## CheckMate Wheel Nut Indicators

- Indicates loose wheel nuts
- Improves safety by visual inspection
- Simple solution to preventing wheel-off incidents
- Made of polyurethane
- Sold in bags of 100

Model	Description	Size
62400	Standard, high-vis yellow	33mm
62400H	High temp, orange	33mm
62419	Standard, high-vis yellow	19mm
62421	Standard, high-vis yellow	21mm
62430	Standard, high-vis yellow	30mm
62432	Standard, high-vis yellow	32mm
62438	Standard, high-vis yellow	38mm
62438H	High temp, orange	38mm
62441	Standard, high-vis yellow	41mm



#62400



#62400H



**IMPROVES  
SAFETY BY  
VISUAL  
INSPECTION**

**SOLD IN BAGS  
OF 100 PCS.**



**PROPER  
USE**



**DANGER  
SIGN OF  
LOOSE  
LUG NUT**



2347 Circuit Way  
Brooksville, FL 34604  
352.799.1111 - sales@ameintl.net

